Page 1 04/10/2018

MIAMI-DADE COUNTY PUBLIC SCHOOLS COMPREHENSIVE SAFETY INSPECTION STATE REQUIREMENTS FOR EDUCATIONAL FACILITIES Facility: Good, Joella C. Elem.

Fish # 2181

Address: 6350 N.W. 188 Terr.

Miami, FL. 33015

Level: Elementary

Inspector:

EMILY BLOCKER

Inspection Date: 05/26/2017

Maintenance Sat.: North

Rule/Para #	Bldg #	Room #	Def. Type	Estim Cost	\$250 - 15 000 10 000 a	Prio rity	Item	Def	iciency description	Scl	hedule A	Date Corrected	Verified By
14 (b)6	46	001	С		SI218111055		Casualty	Portable is in bad shape (port. is not currently occupied.					
14 (b)6	46	002	С		SI218111056		Casualty	Portable is in bad shape (port. is hot currently occupied).					
Facility: Good, Joella C. Elem.					Type 'M' Estimated Cost:			0	Type 'C' Estimated Cost:	0			